

Chuishan Hot Spring Resort

Installation Details

Location: Chuishan Hot Spring Resort

Model:  S100

Area: Hot spring pipe system

Problem: The scale blocked the pipeline and could not be cleaned with chemicals. It must be cleaned manually. The pipe valve parts needed to be replaced regularly.

Installed by: Xinriyuan Company

6 months after installing Vulcan S100

After 6 months of installation, the pipe still has not been cleaned. Through the annual water shutdown inspection to view the effect, the scale in the hot spring water pipe has been significantly reduced.



Chuishan Hot Spring Resort is located in a scenic area and is a large hot spring resort with 144 rooms.