


# BANANA GREENHOUSE KARATAŞ

## Installation details

### Application

Banana Greenhouse Karataş  
Adana, Turkey

### Models

 **Vulcan S25**  
installed in the watering systems

### Purpose

The amount of salt in the irrigation water was above the nutritional values. Therefore, it prevented plant growth. He also wanted to reduce limescale problems in the watering systems.

### Installer

ATILLA YILMAZ TARIM  
DANIŞMANLIK SAN. ve Tic. Ltd. Şti.




## Results

Before using Vulcan, there was salt-induced yellowing of the leaves of the banana plant. After the installation of Vulcan, no new salt-induced yellowing was observed.

This was a very good result for us. Again, the white salinity symptoms observed on the soil surface before using Vulcan disappeared after we started using it.

The blockages experienced in irrigation systems after Vulcan started to be used were not experienced again.

After Vulcan was installed, it was observed that the plants could be fed more easily and the utilization of fertilizer and water increased.



The **VULCAN S25** model was used for irrigation systems. The Vulcan device is built into an outdoor unit.



**Vulcan Impuls bands** are installed in the watering system.