



## INSTALLATION

Altglienicke Housing Association  
in Berlin, Germany

## MODEL SIZE & INSTALLATION AREA



**Vulcan S10** is installed on  
the warm water circulation system



**Vulcan S50** is installed on  
the cold water pipe

## PURPOSE

Solution to solve problems with hard water in the pipe system and  
throughout the domestic water supply.

## RESULTS

After a 6-week Vulcan test, the management is satisfied with the results  
of Vulcan water treatment, and the laundry also confirms better washing  
results.

## INSTALLER


1st SELECTION Chemical-Free Systeme  
[www.1st-selection.eu](http://www.1st-selection.eu)



We decided to keep the technology  
because our tenants and colleagues  
told us that there was actually less  
limescale build-up on sanitary fixtures  
and kitchen appliances. The difference  
was particularly noticeable on the  
kettle, which now only needs to be  
wiped clean and no longer requires  
strong cleaning agents to remove  
limescale. The test period was still  
too short for our fountain, but based  
on our experience in the household,  
we hope to be able to remove the  
limescale deposits from the columns  
more effectively in the future.

Best regards,

T. Franzke  
Authorized signatory



## ABOUT THE COOPERATIVE

Our cooperative was founded in 1957  
and has been synonymous with satisfied  
members and tenants who feel at home  
in their apartments ever since. We own  
apartments in all districts of Berlin-  
Treptow, Prenzlauer Berg, Rudow, and  
Zeuthen.

