




VULCAN TEST REPORT

ALPINE DESIGN RESORT

BERGWELT GRINDELWALD


Location: Hotel Bergwelt Grindelwald, Switzerland
www.bergwelt-grindelwald.com

Model:  S100 water treatment is installed on the water pipe to the sanitary facilities of the Achat house



Result:

When Vulcan was commissioned, water was taken from the same point for a further pH measurement. The lime conversion releases small amounts of CO₂ previously bound to lime. This release reduces the pH value slightly, but measurably. The reduction of 0.15 is a clear result of perfect functioning.



The main purpose as limescale protection for the sanitary installations is guaranteed. This was shown by the PH value measurement.

Installer:  W.Kurt, Bottmingen

