

# VULCAN REPORT




## Condominium Crassier

### INSTALLATION DETAILS

- Location:** Grindelwald Mountains, Switzerland
- Model:** Vulcan S100
- Area:** The Vulcan anti-scale system is installed in the sanitary facilities.
- Results:** After commissioning, another pH measurement was carried out at the same location using the Vulcan system. The change in lime crystallization consumes less CO<sub>2</sub> and lowers the pH value slightly, but measurably. The reduction of 0.15–0.12 is a result of the good functioning.
- Installer:**



W.Kurt  
Bottmingen,  
Schweiz



### pH measurements

PH before installation:



After installation:

