

## **INSTALLATION DETAILS**

**Location:** Four season Village

Ulaanbaatar, Mongolia

**Application:** The Vulcan Anti-Scale Systems

has been installed on all fourblock buildings of the Four

Season Village.

Models: 2 x Vulcan S10 is installed

on the domestic hot water line from the plate heat exchanger.

1 x Vulcan S25 is installed

on the central cold water line.

**Purpose:** Not only is the household's water

supply isrusty, the internal piping systems are also clogged due to

rust.

**Purpose:** After a period of 3 months, the


limescale deposits and rust on the boiler plates were successfully

flushed out and removed.

The water feels softer now and the limescale problems are gone. Also the hardened rust in the pipes has softened, making the

layers thinner.

**Installed by:** Live Water Vulcan LLC













Boiler equipment after 3 months using Vulcan





## **FOUR SEASON VILLAGE**

## **Installation Details**

**Location:** Four season Village

Ulaanbaatar, Mongolia

**Application:** The Vulcan device has been

installed on the four-block buildings of Four season

Village.

Models: 2 x Vulcan S10 is installed

on the domestic hot water from the plate heat

exchanger.

1 x Vulcan S25 is installed

on the central cold water pipe

**Purpose:** The household water supply

is not only rusty, but the internal piping systems are

also clogged due to rust.

**Purpose:** After a period of 3 months,

the scale and rust on the boiler plates had been successfully flushed out and removed. The water has become soft, free of hardness, and the hardened rust inside the pipelines has softened,

causing the layers to thin.

**Installed by:** Live Water Vulcan LLC



