



# Condominium HavblikDenmark

## Installation Details

**Location:** Havblik, Køge, Denmark

**Models:**  **Vulcan S50 Anti-Scale System** is installed on the main water line for the entire piping system for 66 apartments, pumps and water tanks in the basement.



The water piping system before the installtion of Vulcan S50.



The water piping system after the installtion of Vulcan S50.



The Vulcan S50 with copper Impulse bands on the pipe.



66 Apartments Havblik in Køge

### Purpose:

Preventing limescale build-up in the pipes and water heaters of their 66 apartments. Solving the limescale problem with elbow grease and chemistry.

The company was decided against using a traditional water softener system due to its high operational costs, its negative impact on the environment, and its effect on the quality of the water.

### Results:

Limescale does not stick to or build up on surfaces, and it can be easily removed without the use of chemicals. A resident has reported that there is a clear difference in the black sink, with limescale no longer settling on it.

**Installed by:** Techwater Denmark