



Dairy Cattle Stable Nuevo León

VULCAN INSTALLATION DETAILS

Location: Dairy cattle stable Nuevo León
in Torreón, Coahuila, México

Model:  Vulcan S10 Anti-Scale System
is installed on the 2" main water line



Limescale deposits in the water pipe



PURPOSE

The high concentration of calcium in the water causes problems in the cooling tower and mainly in the small boiler. This causes to have to be opened the boiler every 45 days and remove the hard limescale mechanically.

SOLUTION


The eco-friendly and chemical-free Vulcan S10 Anti-Scale System is installed on the main water inlet pipe of the building complex to reduce and prevent limescale build-up.



RESULTS

After installing Vulcan, the boiler was opened after 45 days. „Vulcan works very well.“ We have observed that the limescale became smooth and was easy to remove, which makes maintenance and cleaning much more easier and save a lot of time. „We have less limescale build-up.“

Limescale is easy to remove from the boiler



Limescale deposits can be easily removed from the pipes

