




FOOD PROCESSING PLANT FOR SAUSAGE PRODUCTS




INSTALLATION DETAILS

APPLICATION: Food processing plant *delicatessen*, in Morocco

MODELS:  3000 for the boilers

 3000 for the heat exchanger

 5000 for 2 sterilizers

PROBLEM: Limescale problems in the steam boilers, the sterilizers and the heat exchanger. The client had to use water softener.


RESULT: The water softener is replaced with Vulcan and old scale becomes soft.

INSTALLED BY: STE ETCT INDUSTRIE, Morocco

Vulcan 3000 treats the steam boilers



Before using Vulcan, the steam boilers were non-stopping running for more than 1 year and a small layer of 0.5 mm limescale was found. After 2 months treating with Vulcan, the limescale can be removed easily by a finger.




Vulcan 3000 treats the heat exchanger




Watch the video results:

http://y2u.be/4i_PIKk2ipI



Vulcan 5000 treats 2 sterilizers



Limescale has been built for 15 years. It was not cleaned before installing Vulcan.
After 3 months with Vulcan, we already see the limescale coming out.

