



Vulcan for Grease Traps

3 Months Test Report

in a cake factory in Kanagawa, Japan

Vulcan has a trouble free design and easy installation. The LED light always blinks dependably as it shows the processing conditions.

I have compared the state of the grease trap before and after installing the Vulcan. Before installation, I noticed strong odors when opening the hole. When I opened the hole one month after the installation, no such odors were present.

As for the cleaning intervals, monthly cleaning may now not be required. The effect and cleaning intervals of Vulcan will require an annual observation, however, I believe the amount of cleaning will be reduced remarkably.



Vulcan 5000 was installed in the factory kitchen

February 16th - Start situation before Vulcan was installed



Grease Trap




50 mm thick oil layer



Cleaned Grease Trap

March 22nd 1 month with Vulcan



30 - 40 mm thick oil layer

The second tank

The third tank

The fourth tank

May 18th - 3 months with Vulcan treatment



2nd Tank - 10 mm thick oil layer



1st Tank