





Installation Details

Location: Dongfeng Honda Automobile Co., Ltd.

China

www.dongfeng-honda.com


Area: Automobile casting cooling workshop

Scale problems: The circulating water system for the

production robots was heavily scaled and the large amount of scale in the pipes affected the production line.

Model: Vulcon S25


Installer: Xinriyuan



Dongfeng Honda Automobile Co., Ltd. is an automobile manufacturing company headquartered in China, and a 50:50 joint-venture between Dongfeng Motor Group and Honda Motor Company in Japan. The company was established in 2003 and has three production plants.

Vulcan Effect

After installing Vulcan S25 for **3 months**, the scale on the cooling water side has been significantly reduced, and the use of chemicals and acid has been also reduced. Now only simple manual cleaning is required, which is estimated to save at least US\$4,700 per year.



Vulcan S25 is installed on the main pipeline of the circulating water system for the production robots.

