



Installation Details



Location: Sinoway Carbon Co., Ltd. (Jiangsu)

www.sinowaycarbon.com

Model:  S500

Area: Circulating cooling water pipe

Problem: The new factory in Jiangsu had been operating for more than a year without any water treatment, so it encountered scaling problems, poor cooling effect and reduced water flow.

Result: Before installing Vulcan S500, the scale had not been removed. After more than 6 months, the circulating water system was re-examined and there was no reduction in water flow, proving that no scale had been formed.


Installer: Xinriyuan

Sinoway Carbon Co., Ltd. (Sinoway), a joint venture between Shenzhen Sinoway Investment Holding Co., Ltd. and Dubal Holding LLC, was registered in 2011. Sinoway is mainly engaged in production and sales of calcined petroleum coke (CPC) and with production and sales of Steam as by-product.

Sinoway currently owns and operates two plants, one located in Shandong Province and the other plant is in Jiangsu Province.



Vulcan S500 installed on the circulating cooling water pipe



Vulcan S500