


Galten Vandværk supplies approx. 2900 consumers with clean drinking water. The company supplies water to Galten, Skjørring, Vestermark, Nr. Vissing, Storning and Søballe. Since 2010, the Waterworks has been governed by the Water Sector Act.

The waterworks has six boreholes and is in the process of establishing a test drilling to ensure the best possible supply of clean drinking water in the future. The work is constantly managed and supervised by a modern SRO plant.


Galten Water quality

The waterworks has its own wells (6 main wells) to extract groundwater. The water is analysed to determine its suitability for consumption. This analysis covers substances naturally present in groundwater, as well as any bacteria, pesticide residues and other parameters that may indicate contamination. Galten Vandværk adheres to the control plan established by Skanderborg Municipality. The water has a hardness of 14.2 dH, which is classified as medium hard.



VULCAN INSTALLATION DETAILS

LOCATION



Galten Vandværk Waterwork in Denmark

MODEL



is installed on the main water line for the entire piping system.

www.galtenvand.dk

www.cwt-vulcan.com

